## **Hotkeys Chart**

Here's a list of the hotkeys for some of the most commonly used functions of IPEVO Visualizer:

Function	Мас	Windows
Exit Full Screen	esc	Esc
Toggle between Full Screen and Windowed mode	option + enter	Alt + Enter
Focus	F	F
Show/hide gridlines	D	D
Show/hide camera's status	I	I
Freeze/resume live view	Р	P
Perform the main function of the respective mode	spacebar	spacebar
Toggle between different function modes	cmd + 1~9	Ctrl + 0~9 (Windows 8 and above) Ctrl + 1~9 (Windows 7)